



TEST REPORT

No. : XMIN170601032CCM

Date : Jun.16, 2017

Page: 1 of 3

CUSTOMER NAME: JIANGSU BEIER DECORATION MATERIALS CO., LTD
ADDRESS: NO.999 CHAOYANG ROAD, HENGLIN, WUJIN, CHANGZHOU, JIANGSU PROVINCE

Sample Name : RECLAIMED WILD OAK (WOOD)
Buyer : AIRSTEP FLOORING

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

Test Required : Selected test(s) as requested by applicant
Date of Receipt : Jun.13, 2017
Testing Start Date : Jun.13, 2017
Testing End Date : Jun.16, 2017
Test result(s) : For further details, please refer to the following page(s)
(Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

***** To be continued*****

Signed for
SGS-CSTC Standards Technical
Services Co., Ltd. XM Branch

Civi Huang Authorized Signatory



SGS-CSTC Standards Technical Services Co., Ltd.
Xiamen Branch Testing Center Commercial Construction Material Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Documents.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.31 Xianghong Road, Xiang'an Torch Industrial Zone, Xiamen, Fujian Province, China. 361101 t (86-592) 5765857 f (86-592) 5765380 www.sgs.com.cn
中国·福建·厦门·火炬(翔安)产业区翔虹路31号 邮编:361101 t (86-592) 5765857 f (86-592) 5765380 e sgs.china@sgs.com

TEST REPORT

No. : XMIN170601032CCM

Date : Jun.16, 2017

Page: 2 of 3

Slip resistance (oil-wet ramp test)

Test Method:

DIN 51130:2014-02 Testing of floor coverings - Determination of the anti-slip property - Workrooms and fields of activities with slip danger, walking method - Ramp test

Sample Description:

Flooring, 5pcs of test samples 500mm×190mm (which were cut from original samples) form a testing surface of 500mm×950mm, see the photo(s)

Test Result:

Testing surface: see the photo(s)

Test item(s)	Testing direction	Test result(s)	Classification
Slip resistance (oil-wet ramp test)	Y direction (parallel to width direction)	Critical angle of inclination: 16.2°	R10

Appendix A: Classification of oil-wet ramp test:

Classification	Angle (degrees)
R9	6°≤X≤10°
R10	10°<X≤19°
R11	19°<X≤27°
R12	27°<X≤35°
R13	>35°

***** To be continued*****




TEST REPORT

No. : XMIN170601032CCM

Date : Jun.16, 2017

Page: 3 of 3

Specimen photograph:



Original samples

SGS authenticates the photo on original report only

*****End of report*****

